


MOORES VALLEY

NO PICTURE AVAILABLE



Elevation:	South of Birch Inlet
Position:	?
Strip Directions:	09/27
Strip Lengths:	?
Strip Widths:	?
Strip Slopes:	Up to the East
Strip Surface:	Very Rough with large rocks on the airstrip
Windsock:	No
Strip Markers:	?
Lighting:	?
Landing Fees:	?
Fuel:	?
Owner/ Operator:	?
Special Procedures and Remarks:	Very Rough with large rocks on the airstrip

Information current as at: Not Known

Use of these charts does not absolve the pilot from the responsibility to check on the conditions and servability of the Airstrip