

**SANDFLY**

<b>Elevation:</b>	630M
<b>Position:</b>	42.59 South 147.13 East
<b>Strip Directions:</b>	09/27
<b>Strip Lengths:</b>	700M ( plus 100M over run on the Western End)
<b>Strip Widths:</b>	?
<b>Strip Slopes:</b>	Up hill to the East
<b>Strip Surface:</b>	Grass - usually firm occasionally a bit slushy in winter.
<b>Windsock:</b>	Yes - Two. One at each end of the strip.
<b>Strip Markers:</b>	?
<b>Lighting:</b>	No
<b>Landing Fees:</b>	No
<b>Fuel:</b>	Yes - 10,000 stock
<b>Owner/ Operator:</b>	Contact: Stan Tilly 03 6225 2302
<b>Special Procedures and Remarks:</b>	Permission Required before use. Approaches often turbulent because of trees & gullies. Spot land at windsock from either end. Not before not after but at. Go around early if in doubt. It looks a lot worse than it is.

**Information current as at:** 19-Oct-99